### Accidents/incidents for 2006 Notes on tables

Accident data comes from *Flight International's* own research, sister online publication *Air Transport Intelligence* and from *Flight*'s database service Acas's daily occurrence information. Details of non-fatal incidents are not made available officially by the authorities in many countries, but *Flight* 

*International* continues to list as many incidents as possible, in the interests of maximising the availability of relevant information. Consequently, we accept the non-fatal listing may be weighted against the airlines of those countries that make safety information more readily available.

#### GLOSSARY OF TERMS AND ABBREVIATIONS

| AA airfield approach/early descent<br>AAIB UK Air Accidents<br>Investigation Branch<br>AAL above airfield level<br>ADC air-data computer<br>ADF automatic direction finder<br>AF air force<br>AGL above ground level<br>AMSL above ground level<br>AMSL above mean sea level<br>AOA angle of attack<br>ASB alert service bulletin<br>ASI airspeed indicator<br>ATC air traffic control<br>C climb<br>C-B circuit breaker<br>CFIT controlled flight into terrain<br>CNK cause not known | system<br>EGPWS enhanced ground<br>proximity warning system<br>EGT exhaust gas temperature<br>EICAS engine indicating and crew<br>alerting system<br>ER en route<br>ETOPS extended-range twin<br>operations<br>FAA US Federal Aviation<br>Administration<br>FDR flight data recorder<br>FL flight level = altitude, in hundreds<br>of feet, with international standard<br>pressure-setting (ISA) of 1013.2mb<br>set on altimeter (eg: FL100 =<br>altimeter reading of 10,000ft with | HP high pressure<br>IFR instrument flight rules<br>IMC instrument meteorological<br>conditions<br>ILS instrument-landing system<br>ISA international standard<br>atmosphere = sea level pressure of<br>1013.2mb and standard temp-<br>erature/pressure lapse rate<br>with altitude<br>L landing<br>LP low pressure<br>MEL minimum equipment list<br>MDC McDonnell Douglas<br>MTOW maximum take-off weight<br>NDB non-directional beacon<br>NTSB US National Transportation | RA runway/final approach<br>RNAV area navigation<br>SB service bulletin<br>SID standard instrument departure<br>TAWS terrain awareness and<br>warning system<br>TO take-off<br>TOGA press-button selected take-<br>off/go-around thrust<br>VASI visual approach slope<br>indicator<br>VFR visual flight rules<br>VHF very high frequency<br>VMC visual meteorological<br>conditions<br>VOR VHF omni-range navigation<br>beacon |
|--|--|--|--|
| e e e e e e e e e e e e e e e e e e e  |  |  | • •  |
| DFDR digital flight data recorder  | FMS flight-management system   | PAPI precision approach path   | CONVERSION FACTORS   |
| DME distance-measuring equipment   | G on ground  | indicator  |  |
| ECAM electronic centralised  | GPU ground power unit  | PAX passengers   |  |
| aircraft monitor   | GPWS ground proximity warning system   | PF pilot flying  | 1ft = 0.3m   |
| EFIS electronic flight-instrument  |  | PNF pilot not flying   | 1kt = 1.85km/h   |

| Date   | Carrier  | Aircraft type/registration   | Location  | Fatalities  | Total occupants   | Phase  |
|--|--|--|---|---|---|--|
|  |  |  |   | crew/pax  | crew/pax  |  |
| FATAL AC   | CIDENTS SCHEDUL  | ED PASSENGER FLIGHTS   |   |   |   |  |
| began a clii   | mbing turn right, but  | Airbus A320-200 (EK-32009)<br>a, abandoned a night ILS approach to runwa<br>this became a descending turn and the aircu<br>shows the engines were working at impact,   | raft hit the sea about 6km offshore. 7  | he CIS Interstate Avia  | tion Committee, investi   |  |
| had been d<br>lever for the<br>up along th<br>enough time                                  | eactivated. The initia<br>e port engine and ina<br>e runway." The repor<br>e at their disposal, th   | Airbus A310-300 (F-OGYP)<br>eather with local thunderstorm activity and of<br>I report explains the overrun: "After the touc<br>dvertently actuated it. As a result, the engin<br>t also says the co-pilot lost control of the en<br>e crew did not take proper measures to gee<br>ommittee's role as both regulator and accid   | thdown, while handling thrust reversa<br>e was set in motion. This gave a sub<br>gine performance and failed to inform<br>ar down the engine or switch it off." S   | al system, the captain<br>ostantial forward thrust<br>m the captain of his er<br>7 is contesting the ac                       | mistakenly moved the o<br>to the aircraft which be<br>ror, commenting: "Desp                            | control<br>gan speeding<br>ite having                        |
| Russia's int   | erstate aviation com   | s <b>Tupolev Tu-154M (RA-85185)</b><br>g, the aircraft deep-stalled and spun while tr<br>mittee MAK. Aleksandr Neradko, head of Ru<br>f 39,500ft, and at that point the aircraft – in s  | ussia's Federal Aeronavigation Servi  | ce, says the aircraft cli   | mbed from its cruise all  |  |
| The aircraft<br>porate jet (I<br>at FL370 be<br>of FL370 fo<br>one of its h<br>that robbed | , cruising at its cleare<br>N600XL) on the same<br>ecause it lost commu<br>r which it was cleare<br>orizontal stabilisers, l<br>the pilots of control, | Aereos Boeing 737-800(PR-GTD)<br>ad level of FL370 from Manaus, with its next<br>e airway flying the reciprocal track. The Leg<br>nication with Brasilia air traffic control, and it<br>d between its departure point at Sao Jose of<br>but survived and landed at a nearby military<br>and the wreckage spread implies that the a<br>ons to the Legacy's received Mode C transp | acy, which was flight-planned for the<br>there is no record of a clearance for<br>los Campos and Brasilia. In the collis<br>base with no injuries to its five pass<br>ircraft suffered structural failure befor | Brasilia-Manaus sector<br>the level change from<br>sion the Legacy receiv<br>engers and two pilots.<br>re impact with the gro | or at FL360, is believed<br>the Legacy's previous of<br>ed severe damage to a<br>The Gol 737 suffered v | to have been<br>cruising level<br>winglet and<br>ving damage |
|  | took off in gusty con  | Boeing 737-200 (5N-BFK)<br>ditions as a storm approached. ATC warned<br>in the wind speed and direction. Just after ta   |   | 4/92<br>I immediate take-off ar   | 5/100<br>nd clearance to do so w  | <b>C</b><br>vas  |
| FATAL AC   | CIDENTS NON-SCH  | EDULED PASSENGER FLIGHTS   |   |   |   |  |
| 30 June<br>Hit trees on  | Southern Right Ai<br>approach to the run   | r Charter Cessna Caravan<br>way.   | Vilanculos airport, Mozambiqu   | ue 1/-  | 2/1   | RA   |
|  | the 1,460m runway  | s BAe 146-200 (OY-CRG)<br>33, which was wet and has a displace thresh<br>ion-deployment has not been determined.   | Stord Sorstokken airport, Nor<br>nold giving only a 1,200m landing run  |   | 4/12<br>deployed. The aircraft  | L<br>overran and   |
|  | er Trigana Air Servi<br>flew into a mountain   | ice DHC Twin Otter 300 (PK-YPY)<br>uside at about 10,500ft AMSL.   | Puncak Jaya, Indonesia  | 3/9   | 3/9   | ER   |

| Date         Carrier         Alteral type/registration         Lacation         Patialization         Instruction of controls and the second of  |  |  |   |  |  |   |  |
|--|--|--|---|--|--|---|--|
| FATAL ACCEPTING COMMUTER AND RECOVAL FLIGHTS       12       17       E.R.         Plot made a Warging call and requested diversion 10 Prof Alermi, The alermal was an route from Tole Note Networksey. Us on its alterprise appropria networksey in the alternate alterprise appropria networksey.       21       27       E.R.         Alse at the second line alternate alternate alternate alternate.       21       27       E.R.         Alse at the second line alternate alternate.       211       217       E.R.         Alse at the second line alternate.       211       217       E.R.         Alse at the second line alternate.       211       217       E.R.         Alse at the second line alternate.       211       217       E.R.         Alse at the second line alternate.       211       211       217       E.R.         Alse at the second line alternate.       211   | Date   | Carrier  | Aircraft type/registration  | Location   | Fatalities   | Total occupants   | Phase  |
| 21 January         Sonichite JArryan         Cesana 2008 Carryan (C-GRX2)         N. Port Absern, Canada         1/2         1/2         1/2         F. F.           Hom rade & Mingdocal call and excest down in the induct streem for the indu   |  |  |   |  | crew/pax   | crew/pax  |  |
| Bit and and a Marging call and meginested develon in B Prof Albern <sup>1</sup> . The airclus was or music from Torino to Maccource, Judy on albern statement adjustment or evolution and the abunches adjustment or evolution.   24. March ATERA Cessen 2008 Convent (PGBN) N° Concera alport, Excusion 3 217 217 217   74. March ATERA Cessen 2008 Convent (PGBN) N° Concera alport, Excusion 3 217 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>  |  |  |   |  |  |   |  |
| Jan and Tesher The around to begin and canabies the attraction in a factory.           A Hanch Te All         Let L410 [FF 55]         N S aguarems, Brazi         217         27.7         ER           The attraction on one from Kannes Roo de Jannes Stanses Sumon starrent strends damong direct format in ping ground should 30min aller levels.         407         Kannes         56         RA         Kannes         76         RA         56         RA         76         RA         Kannes         76         RA         76         RA         76         RA         76         RA         76         RA         76         77         77         76         RA         76         76         77         76         RA         76         77         76         RA         76         77         77         76         RA         76         76         77         76         RA         76         76         76         76         76         76         76         76         76         76         76 <td< td=""><td>Pilot made a N</td><td>layday call and requested</td><td>d diversion to Port Alberni. The aircraft v</td><td>was en route from Tofino to Vancouver,</td><td>but on its attempted</td><td>approach to Port Al</td><td>berni it came</td></td<>  | Pilot made a N   | layday call and requested  | d diversion to Port Alberni. The aircraft v   | was en route from Tofino to Vancouver,   | but on its attempted   | approach to Port Al   | berni it came  |
| The alread is non data be flow the Jamese 10% of a James                                 |  |  |   | Nr Cuenca airport, Ecuador   | -/5  | 2/12  | С  |
| During landing in heavy rain the arcraft ran of the investy and suffered "statistand" damage". An 80-year-odg passanger die of a heat statek shortly after the accorder.<br>21 June Vert Allerians C. C. Markov C. 2002 Markov C. 2002 Markov C. 2003 Markov C. 2004 Ma                         |  |  |   |  |  |   | ER   |
| Indux         Protects         Setup 149         Add after setup.         Setup 149         Add after setup.         Setup 149         Add after setup.         Setup 149  |  |  |   |  |  |   |  |
| Just after take-off the aircraft supports to have suffered failure of one of the power lone. In the power lone below crashing, according be whenses.         314         314         AA           24 August         TRACEP         Autorox An 28 (90-CMI)         Ne Bukaru, RP Corpo         314         314         AA           24 August         Commire         Benaharder CR1000E (N413CA)         Lowing base consoleting the LSA NESS of the series of the seris of the seris of the series of the series of the series of the   |  |  | · · · · ·   |  | 3/6  | 3/6   | RA   |
| Hit hörg round in cloud dump the descent for Bukers.         27 August Commit Commit Coll 100ER (M4310.3)       Lexington airport, KY, USA 247 347 30         The C-RL corew acknowledged ATC dearance to take off from Lexington airport main runwy. 22 while laxing, just before the taxi round lexing main runwy. 22 while laxing, just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi round lexing main runwy. 22 while laxing. Just before the taxi runwy. Just here are before the runk runwy. 22 while laxing. Just before the taxi runwy. Just here are before the runwy. Just here are before the runk runwy. 22 while laxing. Just before the laxing while runwy. Just here are before the runk runwy. Just here are before the runwy. Just here arunwhere the here are here are for the runwy. J   |  |  |   | • *  |  |   | С  |
| The CRU erw acknowledged ATC clearance to take off rom Lexingon argorits main (mwy 22 while lawing, just before the taxe to the coverts 32 crosses the threahold began take-off run despite the fact that the numery ledge that act of 00, fight 5191 to Auto a turned to 28, a 1 JORn-tog general avaiton nurvey, and and thready at the act off two stall take-off run despite the fact that the nurvey ledge that the start off to Auto that start and the start off to Auto a turned to Auto and thready at the act off two stall take-off run despite the fact that the nurvey ledge that the start off to Auto a turned to Auto and the Auto Auto Auto Auto Auto Auto Auto Auto  |  |  |   | Nr Bukavu, DR Congo  | 3/14   | 3/14  | AA   |
| of runway 26, according to the US NTSB. In the pre-dawn darkness just after 04:00, flight 5191 to Altonia turned on to 26, a 1070-long general availation runway, and begins it take-off run despite the fact that the nuway lights were not LT. The POR hows that the accreat was all accessing – but not atformer – when it ran over the numay and and through the boundary fonce. A withess on the farm mar where the CR-200 came to rest says it was aitcome, but hit trees and burst into farmes <b>PATA ACCIOENE F 16-UTTS 5 Forumay</b> Air Cargo Carriers Shorts 360-300 (N3735W) Milwauke airport, Wi, USA 3 3 <b>E</b> R The accreal was to undrogs a post-minimonia outs iff that the same they cell off. This aircraft suffered to less of a significant part of the elevel was about a control of the same type (see following jum). It was decided that they should trade-to use of the same type (see following jum). They act cell off. Advance and the same type (see following jum). They act cell off. Advance and the same type (see following jum). They act cell of the same type (see following jum). They act cell of they access the same type (see following jum). They access they access the same type (see following jum).                    |  |  |   |  |  |   |  |
| 5 February         Air Cargo Carriers         Shorts 360-300 (N329W)         Minvakee airport, MU USA         3         3         ER           be aircraft ware to undrogs a post-minitraneous esite find in the same time as another arrors to the same system studered the loss of a significant part of the same system studered the loss of a significant part of the same system studered the loss of a significant part of the same studered the stand.         Image: Comparison of the same studered the stand stand.  | of runway 26,<br>began its take<br>runway end ar   | according to the US NTS<br>off run despite the fact th<br>ad through the boundary f  | B. In the pre-dawn darkness just after 0<br>hat the runway lights were not lit. The FC<br>fence. A witness on the farm near where   | 6:00, flight 5191 to Atlanta turned on to<br>DR shows that the aircraft was still acce   | 26, a 1,070m-long g<br>elerating – but not ai  | general aviation runv<br>rborne – when it ran   | vay, and<br>over the   |
| The alrcraft was to undergo a post-maintenance test flight at the same time as another aircraft of the same type (see following time): twos decided that they should be test with a same type (see following the less of a significant part of the lets of                           |  |  |   | Milwaukee airport, WI, USA   | 3  | 3   | FR   |
| Not longifier reaching 16,0001, bound from DayTon D Harlingen, the juict reported an asymmetric fuel condition arequested radar vactors to the neareal arroral. ATC complete and calered the aircraft outboal be agreed. The arroral fuel dase of the the arroral fuel assemble the arroral fuel assemble the arroral fuel assemble the arroral fuel dases.         16 March       Amerifiaht       Beech C9 (NSARP)       Nr Butten, MT, USA       2       2       R         17 March       KSAMC       Antonix An-74 (UR74038)       Kousseri, Cameroon       6       6       R         18 March       KSAMC       Antonix An-74 (UR74038)       Kousseri, Cameroon       6       6       R         19 March       KSAMC       Antonix An-74 (UR74038)       Kousseri, Cameroon       6       8       R         10 marchinestances, buil attopanco, Chad. On a pre-dawn final approach to th Selashicat attonix with the aircraft on the one the march assemble to the communications equipment from Game.       1       Antonix   | The aircraft wa<br>rendezvous so   | as to undergo a post-mair<br>that air-to-air photograph  | ntenance test flight at the same time as<br>hs of each aircraft could be taken. Durin   | another aircraft of the same type (see 1   | following item). It wa   |   | should   |
| complete and cleared the aircraft to descend to 4.000ft. Within Timin of starting his descent the plot called Mayday stures, and the aircraft eastered as steep due to the ground.       It avanch March Tight       Rev Call Starting Ca  |  |  |   |  | 1  | 1   |  |
| The aircraft, which took off with a light load from Helena bound for Butte lost contact with ATC less than 15min dirt takes-ff. It took two days to find the wreckage.<br>A prior affact if a base charared by the Libyan government from Ukrainian aircraft ranafulfacturer Kharkov Stata Aircraft Amufacturing, which builds the An-74. Ito carry aid<br>from Trapiol via SathaL Libya to NOJamena. Chard on a pro-dwith tinal approach to NOJamena. Chard with we obstructions, the impact appears to have been violen.<br>27 April LGC SkyCongo Convair CV-Sa0F (ZS-SKH) Nr Amis airport, DR Congo 8 6 8 RA<br>The aircraft hat the ground on final approach to is destination at Amisi. It was carrying communications equipment from Ome.<br>28 April King AIr Sevices Cessna 2086 Carravan (ZS-ADL) Rvencori Ms, Uganda 3 3 RA<br>The aircraft, which mod approach to is destination at Amisi. It was carrying communications equipment from Ome.<br>29 Mary Air Soo Tone DHC Twin Otter (99-BAL) Skm Offshore 2 2 2 R<br>Pha aircraft, on a crew training fibr, crashed into the saw while approaching trunway 29 at Sao Tome Inter Constant carabs to the Hole South Hole South 1000 Hole on oute from Coma to Bunia. DR Congo<br>29 Mary Air Soo Tone Other Amis 20 NA NA Congo 6 6 6 R<br>Pha aircraft, on a maintenance, ashandoned in the rist NOW Among and aipcruft.<br>74 Jug Mango Airlines Antonev An-12 Nr Sake, DR Congo 6 6 6 R<br>Pha aircraft, on a same heading until the saw while approaching trunway 29 at Sao Tome Internation across the aircraft and hole governow.<br>74 Ha aircraft and a samehonder dist rist NOR approach to runway 13 at Banington because of bad weither. On its second attempt, according to NTSB Banington Decause of bad weither. On its second attempt, according to NTSB Banington Decause of bad weither. On its second attempt, according to NTSB Banington Decause of bad weither. Succeed All Manufacturing Weith A | complied and o   | cleared the aircraft to desc   | cend to 4,000ft. Within 1min of starting hi   | is descent the pilot called Mayday six tin   | nes, and the aircraft e  |   | to the ground.   |
| 23 April       KSAMC       Antonov An-74 (UR-7403)       Kousseri, Cameroon       6       6       RA         The arrort has been chained by the Lbyan opvermment from Urkinnian airort introkinov State Aircat M. Antonucturing, which builds the An-7A, to carry air from Tipoli via Sabhe. Lbya to NDjamena, Chai. On a pre-dawn final approach to NDjamena, the aircaft crashed sin Bat and whit fwe obstructions, the impact appreas to have been volent.         27 April       LAC SkyCongo       Convair CV-580 (72-SKH)       Nr Antisi airport. DR Congo       8       8         28 April       King Air Sances       Lad CskyCongo       Convair CV-580 (72-SKH)       Nr Antisi airport. DR Congo       8       8         28 April       King Air Sances       Cessna 2686 Carvan (2S-ADI)       Revenzori Mts. Uganda       3       3       ER         28 April       Air San Tome       DHC Twin Otter (S)-BAL)       Rwenzori Mts. Uganda       3       B       RA         7 July       Mango Airlines       Antonov An-12       Nr Sake, DR Congo       6       ER       Encore Bandei and (NSSB)       Nr Heaning Hight, crashed into the sea while approach to runway 12 at Bannightow, beause of bad wather. On its second attempt, according to NTSB integretations of radar information, the aircraft di rob Hight opini is descend to rout the Combrole Missing VOR as per the procedure, but overtained into high ground.         3 August       Air San Carva aircraft di rob tobs groin its descend on the cavery 13 at Bannightowy  |  |  |   |  | -  | 2   |  |
| The aircraft had been chartered by the Libyan government from Ukrainian aircraft manufacturer Kharkov State Aircraft Manufacturing, which builds the An-74, to carry aid from Tripol via Sabha. Libya to ND Jamena, Chaol Can a pre-dawn final approach to ND Jamena, Chaol Canaroo Sabha. Libya to ND Jamena, Chaol Carro ND Jamena, Chaol Carro Sabha (Libya to VD Jamena, Chaol Carro V-SBBT (ZS-SKH) Nr Nr Amila inform LR Congo 8 R The aircraft in the ground on final approach to its destination at Amila It was carrying communications equipment from Goma. 28 April King Air Sarvices Cessna 2068 Carravan (ZS-ADL) Rvenzori Mts, Ugand 3 G K R The aircraft in chartered by the UN World Food Programme, flew into the 167/001 Margarita Feak at about the 13,0001 level en route from Goma to Bunia, DR Congo R A Ari Sao Tome DHC Twin Otter (S9-BAL) Sk m Offshore 2 R R R R The aircraft, on a crew training flight, crashed in the sea while approaching runwy 23 at Sao Tome Island airport. 27 July Mango Antonov An-12 Nr Sake, DR Congo 6 G F R During al fight two ex declared an emergency and ther thore bacesus of engine problems, but the aircraft crashed in the aircraft arcshed in the aircraft arcshed in the aircraft arcshed in the sea while approaching runwy 23 at Sao Tome Island airport. 27 July Mango Antrines Antonov An-12 Nr Sake, DR Congo 6 F R During al fight from Goma the care declared an emergency and ther thore bacesus of engine problems, but the aircraft arcshed into high ground. 44 August AirNow Embrare Banderinate (KS9BA) Nr Bennington, VT, USA 1 A A Aro The aircraft fund in to save from anitenance, alandoned its first VOR approach to runwy 31 at Bennington because of bad wather. On its second attempt, according to NTSB Interpretations of radar information, the aircraft drind hat yasa at 24.0000 rows 272-2007 (HK-S67X) Colombia Song 27                           |  |  |   |  |  | 6   | •  |
| about the circumstances, but athough the land on which the aircraft crashed is fat and with few obstructions, the impact appears to have been violent.          27 April       ACC StyCongo       Convirt CV-SSP (22-SKH)       Nr Amisi airport, DR Congo       3       3       R         28 April       King AF Services       Cessna 2066 Caravan (25-ADL)       Rvenzori Mts, Uganda       3       3       R         The aircraft, chartered by the UN Wolf Cood Programme, flew into the 15,0001 Margaria Paeka at about the 13,0001 Weeler nout form Goma to Buila, DR Congo.       23 May       Air Sao Tome       DHC Twin Ottor (SP-SAL)       Skm offshore       2       2       RA         The aircraft, on thom the crew declared an emergency and their intention to ruturn because of engine problems, but the aircraft crashed into high ground.       An       An         4 August       AirNow       Embrare Bandeirante (N59BA)       Nr Bennington, VT, USA       1       1       AA         The aircraft, positioning to base for maintenance, abandoned its first VOR approach to runway 13 at Bennington because of bad weather. On its second attempt, accordring to NTSB interpretations of radar at first and rubin the aircoraft on begin to second on were the Cambridge VOR as per the procedure, but were there at the diffs.       A         13 August       Air Algere       LocAthere 10:0:30 (7T-HG)       over Placenza, Italy       3       ER         13 August       Air Algere       LocAthere 10:0:30 (7T-HG)       over Placenza, Ital   |  |  |   | ·····  |  | ch builds the An-74, t  |  |
| The aircraft hit the ground on final approach to its destination at Amisi. It was carrying communications equipment from Goma. USE A pril Mang Air Saco Tome and 2000 Programme, flew into the 16,7001t Margarita Peak at about the 13,0001t level en route from Goma to Bunia, DR Congo. 23 May Air Sao Tome DHC Twin Otter (S9-BAL) 3.km offshore 2 0 2 RA The aircraft on a crew training flight, crashed into the sax while approaching runway 29 at Sao Tome Island aipprot. 74 July Mango Airlines Antonov An-12 Nr Sake, DR Congo 6 6 6 ER During a flight from Goma the crew declared an emergency and their intention to return beasuse of engine problems, but the aircraft crashed in tho high ground. 74 August Air Nav Embrare Bandeirante (NSBBA) Nr Bennington, VT, USA 1 1 A A The aircraft, now Embrare Bandeirante (NSBBA) Nr Bennington, VT, USA 1 1 A A The aircraft one cas band ende its first VCR approach to runway 13 at Bennington Baues (and weather. On its second attempt, according to NTS Binterpretations of radar information, the aircraft did not begin its descent over the Cambridge VOR as per the procedure, but overhead the airfield, and it continued outbound on the same heading until it hits ground. To selece the advect the aircraft at all marks at 24,0000 from Craft Baues (Bring Air Sale Craft Inthe Ground at high speed in a steep nose-down attitude. 78 Now Erefore Aerosure Colombia Boeing 727-200F (HK-3667X) Colombia 5 5 AA The aircraft hind an attenna during its approach and crashed. 79 Deveram her unway on landing. The crew marks and crashed. 70 Corental Accident The Sale Craft Profegistration Location Injuries approach to runway at The Aircraft Weak and crashed. 70 Corental Accident Sale Barght and Crashed Craft Barght Barght and Crashed Craft Barght Bar                           | from Tripoli via   | a Sabha, Libya to N'Djam   | ena, Chad. On a pre-dawn final approad  | ch to N'Djamena, the aircraft crashed o  | n the Cameroon side  | e of the Chari river. L   |  |
| 28 April       King Air Services       Cessna 206B Caravan (ZS-ADL)       River corring the support of the second to the secon   |  |  |   |  |  | 8   | RA   |
| 23 May       Air Sao Tome       DHC Twin Otter (S9-BAL)       3km offshore       2       2       RA         The arcraft, on a crew training flight, creashed into the sea while approaching runway 29 at Sao Tome Island airport.       7       Sixe, DR Congo       6       6       RA         During a flight from Gona the crew declared an emergency and their intention to return because of engine problems, but the aircraft carshed into high ground.       Air Sake, DR Congo       6       6       RA         4 August       AirNow       Embarder Randerinate (NS98 M). Nr Bennington, VT, USA       1       A         An The aircraft, individe and information, the aircraft dind to begin its descent over the Cambridge VOR as per the procedure, but overhed at eartifield, and it continue to ubudund on the same heading until it hit rising ground.       3       ER         13 August       Air Algerie       Lockheed L-100-30 (TrVHG)       over Piacenza, Italy       3       3       ER         16 aircraft was at 24.0001 over Italy en cute Algerie-Frankfurt when the autopilot fail aler was activated. Shortly afterwards the autopilot fail aler the as activated. Shortly afterwards the autopilot disconnected, the aircraft information, if (RA-SGRF)       Colombia       5       Aa         16 Noverhoft was at 24.0001 over Italy en cute Algerie-Frankfurt when the autopilot fail aler the sa activated. Shortly afterwards the autopilot disconnected, the aircraft information, if (RA-SGRF)       Colombia       5       Aa       Aa  | 28 April   | King Air Services  | Cessna 206B Caravan (ZS-ADL)  | Rwenzori Mts, Uganda   | 3  |   |  |
| 7 July       Mango Airlines       Antonov An-12       Nr Sake, DR Congo       6       6       ER         During a flight from Goma the crew declared an emergency and their intention to return because of engine problems, but the aircraft crashed into high ground.       August       AirNow       Embrare Bandeirante (NSSBA)       Nr Bennington, VT, USA       1       AA         The aircraft, positioning to base for maintenance, abandoned its first VCR approach to runway 13 at Bennington because of bad weather. On its second attempt, according to NTSB interpretations of radar information, the aircraft di not begin its descent over the Cambridge VOR as per the procedure, but overhead the airfield, and it continued outbound on the same heading until it hit rising ground.         13 August       Air Algerie       Lockheed L-100-30 (Tr-VHG)       over Piacenza, Italy       3       3       ER         The aircraft was at 24,000ft over taly en route Algiers, Frankutr when the autopilot fail allert was activated. Shortly afterwards the autopilot fail allost was at 24,000ft over taly en route Algiers, Frankutr when the autopilot fail allert was activated. Shortly afterwards the autopilot fail alloscome tale.       Secondata       ER         18 November       Aerosuce Colombia       Boeing 727-200F (HK-3667X)       Colombia       5       5       AA         14 arcraft type/registration       Location       Injuries       Total occupants       Phase         0 verran the runway on landing. The crew made a precautionary return to Bangkok airport, fualiand<  | 23 May   | Air Sao Tome   | DHC Twin Otter (S9-BAL)   | 3km offshore   |  |   | •  |
| 4 August       AirNow       Embrare Bandeirante (N59BA)       Nr Bennington, VT, USA       1       1       AA         The aircraft, positioning to base for maintenance, abandnoed its first VOR approach to runway 13 at Bennington because of bad weather. On its second autempt, according to NTSB interpretations of radar information, the aircraft did not begin it did not begin did not begin it dit did not begin it dit dit did not did did n  | 7 July   | Mango Airlines   | Antonov An-12   | Nr Sake, DR Congo  |  |   |  |
| The aircraft was at 24,000ft over Italy en route Algiers-Frankfurt when the autopilot fail allert was activated. Shortly afterwards the autopilot disconnected, the aircraft almost instantly departed stable flight and 75s later it hit the ground at high speed in a steep nose-down attitude.         18 November       Aerosucre Colombia       Boeing 727-200F (Hk-3667X)       Colombia       5       5       AA         NON-FATAL ACCIDENTS AND INCIDENTS, SCHEDULED PASSENGER FLIGHTS         Date       Carrier       Aircraft type/registration       Location       Injuries       Total occupants       Phase         S February       Nok Air       Boeing 737-400 (HS-TDD)       Bangkok airport, Sumba, Indonesia       -/       7136       ER         Total occupants       Phase         Crew/pax         5 February       Nok Air       Boeing 737-400 (HS-TDD)       Bangkok airport, Sumba, Indonesia       -/       7136       ER         Total occupants       Phase         Crew/pax         Total occupants       Phase         Crew/pax         1       7  | 4 August<br>The aircraft, po<br>to NTSB interp   | AirNow<br>ositioning to base for main  | Embraer Bandeirante (N59BA)<br>ntenance, abandoned its first VOR appr   | Nr Bennington, VT, USA<br>oach to runway 13 at Bennington beca   | 1  | 1   | AA   |
| The aircraft hit an antenna during its approach and crashed.         NON-FATAL ACCIDENTS AND INCIDENTS, SCHEDULED PASSENGER FLIGHTS         Total occupants       Phase         Crew/pax       Crew/pax       Crew/pax         S February Nok Air       Boeing 737-400 (HS-TDD)       Bangkok airport, Thailand       -/2       5/110       L         Overran the runway on landing. The crew made a precautionary return to Bangkok after taking off for Phuket, and the crew reported brake problems on landing.       Total occupants       Phase         The forew became lost en route from Jakarta to Makassar, and diverted to land on the 1,600m runway at Tobulaka airfield on Sumba island, the airline says. The airline's president says he believes the navigation equipment had nothing wrong with it.       S February Air France       Airbus A340-300 (F-GLZO)       Douala airport, Cameroon       -/-       2/7       L         After touchdown and the apolication of reverse thrust the aircraft spene"4" and left the runway, sustaining substantial damage. Before take-off the left thrust reverser was understood not to be serviceable.         27       L         Airbus A340-300 (F-GLZO)       Douala airport, Cameroon       -/-       6/138 <td< td=""><td>42 A</td><td>ne same heading until it h</td><td>nit rising ground.</td><td><b>C</b> .</td><td></td><td>head the airfield, and</td><td>d it continued</td></td<>  | 42 A   | ne same heading until it h   | nit rising ground.  | <b>C</b> .   |  | head the airfield, and  | d it continued   |
| Date       Carrier       Aircraft type/registration       Location       Injuries       Total occupants       Phase         5 February       Nok Air       Boeing 737-400 (HS-TDD)       Bangkok airport, Thailand       -/2       5/110       L         Overran the runway on landing. The crew made a precautionary return to Bangkok after taking off for Phuket, and the crew reported brake problems on landing.       The forew became lost en route from Jakarta to Makasasar, and diverted to land on the 1,600m runway at Tobulaka airfield on Sumba island, the airline says. The airline's president says he believes the navigation equipment had nothing wrong with it.       Prace       Airbus A340-300 (F-GLZO)       Douala airport, Cameroon       -/-       ?/?       L         The crew became lost on the form Jakarta to Makasasar, and diverted to land on the main gear touched the runway before the aircraft climbed away. Alter a successful second attempt to land, the landing gear was cleared by the airline's ground crew. Cameroon authorities, however, held the aircraft for some time.       -/-       6/138       L         4 March       Lion Air       Boeing 737-800 (EI-DHX)       Knock airport, Ireland       -/-       6/138       L         23 March       Ryanair       Boeing 737-800 (EI-DHX)       Knock airport, Ireland       -/-       6/138       L         Alfer touchdown and the application of reverse thrust the aircraft slewed right and left the runway, sustaining substantial damage. Before take-offf the left thrust reversers was understood no  | The aircraft wa  | ne same heading until it h<br><b>Air Algerie</b><br>as at 24,000ft over Italy e  | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autor  | over Piacenza, Italy<br>pilot fail alert was activated. Shortly afte   | 3  | head the airfield, and  | d it continued   |
| Crew/pax       Crew/pax         5 February       Nok Air       Boeing 737-400 (HS-TDD)       Bangkok airport, Thailand       -/2       5/110       L         Overran the runway on landing. The crew made a precautionary return to Bangkok after taking off for Phuket, and the crew reported brake problems on landing.       11 February       Adam Air       Boeing 737-300 (PK-KKE)       Tobulaka airport, Sumba, Indonesia -/-       7/136       ER         The crew became lost en route from Jakarta to Makassar, and diverted to land on the 1,600m runway at Tobulaka airfield on Sumba island, the airline says. The airline's president says he believes the navigation equipment had nothing wrong with it.       15 February       Air France       Airbus A340-300 (F-GLZO)       Doual airport, Cameroon       -/-       ?/?       L         The captain decided to go around again late on final approach in a rainstorm, and the main gear touched the runway before the aircraft climbed away. After a successful second attempt to land, the landing gear was cleared by the airline's ground crew. Cameroon authorities, however, held the aircraft for some time.       4         4 March       Lion Air       Boeing 737-800 (EI-CHKUW)       Surabaya airport Indonesia       -/-       6/138       L         23 March       Ryanair       Boeing 737-800 (EI-DHX)       Knock airport, Ireland       -/-       6/138       L         After touchdown and the application of reverse thrust the aircraft sewed right and left the runway, sustaining substantial damage   | The aircraft wa<br>instantly depar<br>18 November  | he same heading until it h<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia  | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autor<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)  | over Piacenza, Italy<br>pilot fail alert was activated. Shortly after<br>steep nose-down attitude.   | 3<br>erwards the autopilot   | head the airfield, and<br>3<br>disconnected, the a  | d it continued<br>ER<br>ircraft almost   |
| Overran the runway on landing. The crew made a precautionary return to Bangkok after taking off for Phuket, and the crew reported brake problems on landing.         11 February       Adam Air       Boeing 737-300 (PK-KKE)       Tobulaka airport, Sumba, Indonesia       -/-       7/136       ER         The crew became lost en route from Jakarta to Makassar, and diverted to land on the 1,600m runway at Tobulaka airfield on Sumba island, the airline says. The airline's president says he believes the navigation equipment had nothing wrong with it.       15 February       Air France       Airbus A340-300 (F-GLZO)       Douala airport, Cameroon       -/-       ?/?       L         The captain decided to go around again late on final approach in a rainstorm, and the main gear touched the runway before the aircraft for some time.       4 March       Lion Air       Boeing MD-82 (PK-LMW)       Surabaya airport Indonesia       -/-       6/138       L         After touchdown and the application of reverse thrust the aircraft slewed right and left the runway, sustaining substantial damage. Before take-off the left thrust reverser was understood not to be serviceable.       23 March       Ryanair       Rogeing 737-800 (EI-DHX)       Knock airport, Ireland       -/-       6/138       L         A Ryanair Boeing 737-800 on approach to Knock airport, Ireland, 'only marginally avoided" controlled flight into terrain, according to the Irish Air Accident Investigation Unit (AAIU) report on the incident. The AAIU says the principal cause was that, during an ILS approach to runway 27 from which the crew were planning to break off to carry  | The aircraft wa<br>instantly depar<br><b>18 November</b><br>The aircraft hit<br><b>NON-FATAL</b>   | he same heading until it h<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia<br>an antenna during its ap  | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autop<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)<br>proach and crashed.   | over Piacenza, Italy<br>bilot fail alert was activated. Shortly after<br>steep nose-down attitude.<br>Colombia   | 3<br>erwards the autopilot<br>5  | head the airfield, and<br>3<br>disconnected, the a<br>5   | d it continued<br>ER<br>ircraft almost<br>AA   |
| The crew became lost en route from Jakarta to Makassar, and diverted to land on the 1,600m runway at Tobulaka airfield on Sumba island, the airline says. The airline's president says he believes the navigation equipment had nothing wrong with it.         15 February Air France Airbus A340-300 (F-GLZO) Douala airport, Cameroon -/- ?/? L         The captain decided to go around again late on final approach in a rainstorm, and the main gear touched the runway before the aircraft climbed away. After a successful second attempt to land, the landing gear was cleared by the airline's ground crew. Cameroon authorities, however, held the aircraft for some time.         4 March Lion Air Boeing MD-82 (PK-LMW) Surabaya airport Indonesia -/- 6/138 L         After touchdown and the application of reverse thrust the aircraft slewed right and left the runway, sustaining substantial damage. Before take-off the left thrust reverser was understood not to be serviceable.         23 March Ryanair Boeing 737-800 (EI-DHX) Knock airport, Ireland -/- 6/138 L         ARyanair Boeing 737-800 on approach to Knock airport, Ireland, "only marginally avoided" controlled flight into terrain, according to the Irish Air Accident Investigation Unit (AAIU) report on the incident. The AAIU says the principal cause was that, during an ILS approach to runway 27 from which the crew were planning to break off to carry out a circling approach to the reciprocal runway, both pilots fixated on reprogramming the FMC while the aircraft continued its descent. When the aircraft emerged from the cloudbase it was low, fast, and unconfigured for landing. They had originally programmed if or an NDB approach for 09. A contributory cause as a "systemic failure" at the airline and at chart supplier J  | The aircraft wa<br>instantly depar<br><b>18 November</b><br>The aircraft hit<br><b>NON-FATAL</b>   | he same heading until it h<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia<br>an antenna during its ap<br>ACCIDENTS AND INCID   | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autop<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)<br>proach and crashed.<br>JENTS, SCHEDULED PASSENGER FL  | over Piacenza, Italy<br>pilot fail alert was activated. Shortly after<br>steep nose-down attitude.<br>Colombia<br>IGHTS<br>Location  | 3<br>erwards the autopilot<br>5<br>Injuries  | head the airfield, and<br>3<br>disconnected, the a<br>5<br>Total occupants  | d it continued<br>ER<br>ircraft almost<br>AA   |
| The captain decided to go around again late on final approach in a rainstorm, and the main gear touched the runway before the aircraft climbed away. After a successful second attempt to land, the landing gear was cleared by the airline's ground crew. Cameroon authorities, however, held the aircraft for some time.4 MarchLion AirBoeing MD-82 (PK-LMW)Surabaya airport Indonesia-/-6/138LAfter touchdown and the application of reverse thrust the aircraft slewed right and left the runway, sustaining substantial damage. Before take-off the left thrust reverser was understood not to be serviceable.23 MarchRyanairBoeing 737-800 (EI-DHX)Knock airport, Ireland-/-6/138LA Ryanair Boeing 737-800 on approach to Knock airport, Ireland, "only marginally avoided" controlled flight into terrain, according to the Irish Air Accident Investigation Unit (AAIU) report on the incident. The AAIU says the principal cause was that, during an ILS approach to runway 27 from which the crew were planning to break off to carry out a circling approach to the reciprocal runway, both pilots fixated on reprogramming the FMC while the aircraft continued its descent. When the aircraft emerged from the cloudbase it was low, fast, and unconfigured for landing. They had originally programmed if or an NDB approach for 0.9. A contributory cause as a "systemic failure" at the airline and at chart supplier Jeppesen, which meant the pilots did not have up-to-date information about the navigational aids at Knock.29 MarchEirjetAirbus A320Ballykelly airfield, Northern Ireland -/-6/39L  | The aircraft wa<br>instantly depart<br>18 November<br>The aircraft hit<br>NON-FATAL /<br>Date<br>5 February  | he same heading until it h<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia<br>an antenna during its ap<br>ACCIDENTS AND INCID<br>Carrier<br>Nok Air   | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autop<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)<br>proach and crashed.<br>ENTS, SCHEDULED PASSENGER FL<br>Aircraft type/registration<br>Boeing 737-400 (HS-TDD)  | over Piacenza, Italy<br>oilot fail alert was activated. Shortly after<br>steep nose-down attitude.<br>Colombia<br>.IGHTS<br>Location<br>Bangkok airport, Thailand  | 3<br>enwards the autopilot<br>5<br>Injuries<br>crew/pax<br>-/2   | head the airfield, and<br>adisconnected, the a<br>5<br>Total occupants<br>crew/pax<br>5/110   | ER<br>ircraft almost<br>AA<br>Phase<br>L   |
| After touchdown and the application of reverse thrust the aircraft slewed right and left the runway, sustaining substantial damage. Before take-off the left thrust reverser was understood not to be serviceable.         23 March       Ryanair       Boeing 737-800 (EI-DHX)       Knock airport, Ireland       -/-       6/138       L         A Ryanair Boeing 737-800 on approach to Knock airport, Ireland, "only marginally avoided" controlled flight into terrain, according to the Irish Air Accident Investigation Unit (AAIU) report on the incident. The AAIU says the principal cause was that, during an ILS approach to runway 27 from which the crew were planning to break off to carry out a circling approach to the reciprocal runway, both pilots fixated on reprogramming the FMC while the aircraft continued its descent. When the aircraft emerged from the cloudbase it was low, fast, and unconfigured for landing. They had originally programmed it for an NDB approach for 09. A contributory cause was a "systemic failure" at the airline and at chart supplier Jeppesen, which meant the pilots did not have up-to-date information about the navigational aids at Knock.         29 March       Eirjet       Airbus A320       Ballykelly airfield, Northern Ireland -/-       6/39       L  | The aircraft wa<br>instantly depart<br>18 November<br>The aircraft hit<br>NON-FATAL /<br>Date<br>5 February<br>Overran the ru<br>11 February<br>The crew beca  | he same heading until it h<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia<br>an antenna during its ap<br>ACCIDENTS AND INCID<br>Carrier<br>Nok Air<br>Inway on landing. The cre<br>Adam Air<br>ame lost en route from Ja   | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autop<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)<br>proach and crashed.<br>JENTS, SCHEDULED PASSENGER FL<br>Aircraft type/registration<br>Boeing 737-400 (HS-TDD)<br>av made a precautionary return to Bang<br>Boeing 737-300 (PK-KKE)<br>karta to Makassar, and diverted to land   | over Piacenza, Italy<br>pilot fail alert was activated. Shortly after<br>steep nose-down attitude.<br>Colombia<br>.IGHTS<br>Location<br>Bangkok airport, Thailand<br>Ikok after taking off for Phuket, and the<br>Tobulaka airport, Sumba, Indonesia<br>on the 1,600m runway at Tobulaka airfi   | 3<br>enwards the autopilot<br>5<br>Injuries<br>crew/pax<br>-/2<br>crew reported brake<br>-/-   | head the airfield, and<br>adisconnected, the a<br>5<br>Total occupants<br>crew/pax<br>5/110<br>problems on landim<br>7/136  | ER<br>ircraft almost<br>AA<br>Phase<br>L<br>g.<br>ER                                 |
| A Ryanair Boeing 737-800 on approach to Knock airport, Ireland, "only marginally avoided" controlled flight into terrain, according to the Irish Air Accident Investigation Unit<br>(AAIU) report on the incident. The AAIU says the principal cause was that, during an ILS approach to runway 27 from which the crew were planning to break off to carry<br>out a circling approach to the reciprocal runway, both pilots fixated on reprogramming the FMC while the aircraft continued its descent. When the aircraft emerged<br>from the cloudbase it was low, fast, and unconfigured for landing. They had originally programmed it for an NDB approach for 09. A contributory cause as a "systemic fail-<br>ure" at the airline and at chart supplier Jeppesen, which meant the pilots did not have up-to-date information about the navigational aids at Knock.<br>29 March <u>Eirjet</u> <u>Airbus A320</u> <u>Ballykelly airfield, Northern Ireland</u> -/- <u>6/39</u> L   | The aircraft wa<br>instantly depart<br>18 November<br>The aircraft hit<br>NON-FATAL /<br>Date<br>5 February<br>Overran the ru<br>11 February<br>The crew beca<br>president says<br>15 February<br>The captain definition   | he same heading until it h<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia<br>an antenna during its ap<br>ACCIDENTS AND INCID<br>Carrier<br>Nok Air<br>Inway on landing. The cree<br>Adam Air<br>ame lost en route from Ja<br>he believes the navigation<br>Air France<br>ecided to go around agair   | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autop<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)<br>proach and crashed.<br>ENTS, SCHEDULED PASSENGER FL<br>Aircraft type/registration<br>Boeing 737-400 (HS-TDD)<br>aw made a precautionary return to Bang<br>Boeing 737-300 (PK-KKE)<br>karta to Makassar, and diverted to land<br>on equipment had nothing wrong with it.<br>Airbus A340-300 (F-GLZO)<br>n late on final approach in a rainstorm, a   | over Piacenza, Italy<br>oilot fail alert was activated. Shortly after<br>steep nose-down attitude.<br>Colombia<br>.IGHTS<br>Location<br>Bangkok airport, Thailand<br>kok after taking off for Phuket, and the<br>Tobulaka airport, Sumba, Indonesia<br>on the 1,600m runway at Tobulaka airfi<br>Douala airport, Cameroon<br>and the main gear touched the runway I  | 3<br>enwards the autopilot<br>5<br>Injuries<br>crew/pax<br>-/2<br>crew reported brake<br>-/-<br>ield on Sumba island<br>-/-<br>before the aircraft cli   | a disconnected, the a<br>disconnected, the a<br>5<br>Total occupants<br>crew/pax<br>5/110<br>problems on landin<br>7/136<br>d, the airline says. Th<br>?/?<br>mbed away. After a s  | ER<br>ircraft almost<br>AA<br>Phase<br>L<br>g.<br>ER<br>ne airline's<br>L            |
|  | The aircraft wa<br>instantly depart<br>18 November<br>The aircraft hit<br>NON-FATAL /<br>Date<br>5 February<br>Overran the ru<br>11 February<br>The crew beca<br>president says<br>15 February<br>The captain de<br>second attemp<br>4 March<br>After touchdow   | he same heading until it h<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia<br>an antenna during its ap<br>ACCIDENTS AND INCID<br>Carrier<br>Nok Air<br>Inway on landing. The cre<br>Adam Air<br>ame lost en route from Ja<br>the believes the navigatio<br>Air France<br>acided to go around again<br>to to land, the landing gea<br>Lion Air<br>vn and the application of i  | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autop<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)<br>pproach and crashed.<br>ENTS, SCHEDULED PASSENGER FL<br>Aircraft type/registration<br>Boeing 737-400 (HS-TDD)<br>ew made a precautionary return to Bang<br>Boeing 737-300 (PK-KKE)<br>karta to Makassar, and diverted to land<br>on equipment had nothing wrong with it.<br>Airbus A340-300 (F-GLZO)<br>late on final approach in a rainstorm, a<br>ar was cleared by the airline's ground cre<br>Boeing MD-82 (PK-LMW)   | over Piacenza, Italy<br>pilot fail alert was activated. Shortly after<br>steep nose-down attitude.<br>Colombia<br>.IGHTS<br>Location<br>Bangkok airport, Thailand<br>ukok after taking off for Phuket, and the<br>Tobulaka airport, Sumba, Indonesia<br>on the 1,600m runway at Tobulaka airff<br>Douala airport, Cameroon<br>and the main gear touched the runway I<br>ew. Cameroon authorities, however, he<br>Surabaya airport Indonesia  | 3<br>enwards the autopilot<br>5<br>Injuries<br>crew/pax<br>-/2<br>crew reported brake<br>-/-<br>ield on Sumba island<br>-/-<br>before the aircraft cli<br>ld the aircraft for son<br>-/-   | head the airfield, and<br>adisconnected, the a<br>5<br>Total occupants<br>crew/pax<br>5/110<br>problems on landin<br>7/136<br>d, the airline says. Th<br>?/?<br>mbed away. After a sine time.<br>6/138  | ER<br>AA<br>Phase<br>L<br>g.<br>ER<br>he airline's<br>L<br>successful<br>L           |
|  | The aircraft wa<br>instantly depart<br>18 November<br>The aircraft hitt<br>NON-FATAL /<br>Date<br>5 February<br>Overran the ru<br>11 February<br>The crew beca<br>president says<br>15 February<br>The captain de<br>second attemp<br>4 March<br>After touchdow<br>understood no<br>23 March<br>A Ryanair Boe<br>(AAIU) report<br>out a circling a<br>from the cloud | ne same heading until it F<br>Air Algerie<br>as at 24,000ft over Italy e<br>ted stable flight and 75s<br>Aerosucre Colombia<br>an antenna during its ap<br>ACCIDENTS AND INCID<br>Carrier<br>Nok Air<br>Inway on landing. The cre<br>Adam Air<br>ame lost en route from Ja<br>he believes the navigatio<br>Air France<br>ecided to go around agair<br>t to land, the landing gea<br>Lion Air<br>wn and the application of in<br>t to be serviceable.<br>Ryanair<br>ing 737-800 on approach<br>on the incident. The AAIU<br>pproach to the reciprocal<br>base it was low, fast, and | hit rising ground.<br>Lockheed L-100-30 (7T-VHG)<br>n route Algiers-Frankfurt when the autop<br>later it hit the ground at high speed in a<br>Boeing 727-200F (HK-3667X)<br>proach and crashed.<br>ENTS, SCHEDULED PASSENGER FL<br>Aircraft type/registration<br>Boeing 737-400 (HS-TDD)<br>aw made a precautionary return to Bang<br>Boeing 737-300 (PK-KKE)<br>karta to Makassar, and diverted to land<br>on equipment had nothing wrong with it.<br>Airbus A340-300 (F-GLZO)<br>n late on final approach in a rainstorm, a<br>ar was cleared by the airline's ground cre<br>Boeing MD-82 (PK-LMW)<br>reverse thrust the aircraft slewed right a<br>Boeing 737-800 (EI-DHX)<br>n to Knock airport, Ireland, "only margina<br>b says the principal cause was that, duri<br>1 runway, both pilots fixated on reprogran<br>4 unconfigured for landing. They had origon | over Piacenza, Italy<br>oitot fail alert was activated. Shortly after<br>steep nose-down attitude.<br>Colombia<br>.IGHTS<br>Location<br>Bangkok airport, Thailand<br>kok after taking off for Phuket, and the<br>Tobulaka airport, Sumba, Indonesia<br>on the 1,600m runway at Tobulaka airff<br>Douala airport, Cameroon<br>and the main gear touched the runway I<br>ew. Cameroon authorities, however, he<br>Surabaya airport Indonesia<br>ind left the runway, sustaining substanti<br>Knock airport, Ireland<br>ally avoided" controlled flight into terrain<br>ng an ILS approach to runway 27 form<br>mming the FMC while the aircraft conting<br>ginally programmed it for an NDB approx | 3<br>enwards the autopilot<br>5<br>Injuries<br>crew/pax<br>-/2<br>crew reported brake<br>-/-<br>ield on Sumba island<br>-/-<br>before the aircraft cli<br>ld the aircraft for som<br>-/-<br>ial damage. Before ta<br>-/-<br>h, according to the Iri<br>which the crew were<br>nued its descent. W/ | head the airfield, and<br>disconnected, the a<br>5<br>Total occupants<br>crew/pax<br>5/110<br>problems on landim<br>7/136<br>d, the airline says. Th<br>?/?<br>mbed away. After a<br>ne time.<br>6/138<br>ake-off the left thrust<br>6/138<br>sh Ar Accident Invest<br>e planning to break c<br>en the aircraft emer<br>but or base a " | ER<br>Phase<br>L<br>g.<br>ER<br>te airline's<br>L<br>successful<br>L<br>reverser was |

| Date  | Carrier   | Aircraft type/registration  | Location   | Injuries<br>crew/pax  | Total occupants<br>crew/pax  | Phase                                 |
|---|---|---|--|---|--|---------------------------------------|
|   |   | <b>Boeing 777</b><br>ainian, Polish and Czech airspace, the<br>vere sent to intercept it. Vietnam Airlines  |  |   |  | ER<br>ch ATC, but                     |
| 15 May  | Lufthansa   | Boeing 747-400 (D-ABTK)<br>he nosewheel for pushback, the nose g  | Frankfurt Main airport, Germany  | -/-   | 16/242   | G<br>as unclear.                      |
| "about 1min" b<br>before it was c<br>Peebles, Ohio<br><b>2 June</b> | ecause the continuous ig<br>leared back into service.<br>test site. Since its introdu<br>American Airlines          | Airbus A330-200<br>s momentarily flamed out during descention had been selected, along with en<br>GE says it is still working on finding out<br>iction in 1985 the series has suffered ei<br>Boeing 767-200ER (N330AA)<br>1 General Electric CF-80A engine, the | gine anti-icing, for the descent. The Cl<br>t the cause, and it has been conductin<br>ight double flame-outs in icing conditio<br>Los Angeles airport, CA, USA   | ninese authorities too<br>g ground icing tests o<br>ns during gradual de<br>-/-       | ok a week to check the on CF6-80 series engesternts.                   | ne aircraft<br>gines at its<br>G      |
| wing and flaps<br>tank and a fuel                                   | and the rear fuselage. It line, and causing fuel to   | appears that a high-pressure turbine di spill on to the apron. As a result of the   | sk failed at about 90% power because<br>fire damage the aircraft is expected to  | of an undetected cra<br>be a write-off.   | ack. Debris puncture   | d a wing fue                          |
|   |   | Boeing 737-300 (B-2979)<br>eavy rain, according to the civil aviation   |  | -/-   | 10/78  | L                                     |
|   |   | Boeing 737-400 (EI-COI)<br>g the take-off run. The aircraft landed s  | •  | -/-   | ?/?  | то                                    |
| <b>20 June</b><br>Nose gear faile                                   | American Airlines<br>ed to deploy at the end of   | Boeing MD-83 (N961TW)<br>a flight from Los Angles. This was cont  | Chicago O'Hare airport, IL, USA<br>firmed after a tower fly-by, and the airc   | -/-<br>raft landed safely wit   | 5/131<br>h the nose gear retra   | L<br>acted.                           |
| <b>23 June</b><br>The aircraft ove                                  | AMC Aviation<br>erran runway 13 and des   | Boeing MD-83 (SU-BOZ)<br>troyed its landing gear on arrival from K  | Juba airport Sudan<br>(hartoum.  | -/-   | 5/9  | L                                     |
|   |   | <b>Tupolev Tu-154M (EP-LBR)</b><br>OL which is closed for repairs and exte<br>R, the first runway that becomes visible  |  |   |  | L<br>ed, on a VOF                     |
| <b>15 July</b><br>While taxiing fr                                  | Thai Airways<br>om the terminal to depart   | Boeing 747-400 (HS-TGY)<br>t for Rome and Bangkok, the right wing   | <b>Madrid Barajas airport, Spain</b><br>tip destroyed the tail of a stationary E   | -/-<br>mbraer ERJ-135ER.  | ?/?  | G                                     |
| <b>23 July</b><br>The NTSB beli<br>when the Atlas<br>estimating the | United Airlines<br>eves a controller error ca<br>freighter crossed runway<br>aircraft came within 200-              | Boeing 737-300<br>used a runway incursion involving a Ur<br>/ 27L (after landing on 14R) after United<br>300ft of each other, although this is und<br>d the 737's undercarriage. "The FAA ha  | Chicago O'Hare airport, IL, USA<br>aited Airlines Boeing 737-300 and an A<br>d flight 1015 was cleared for take-off or<br>lerstood to be the distance between th | <b>-/-</b><br>tlas Air 747. The inci<br>n 27L. The agency sa<br>e fuselages as the 73 | ays the 737 took off<br>37 passed above the                            | over the 747<br>747, not the          |
| 8 August<br>The forward let   | TAM<br>t passenger door opened  | Fokker 100 (PT-MQN)<br>I just after take-off and was ripped off b   | São Paulo Conghonas airport, Brazil<br>y the slipstream. The aircraft returned   |   | 5/79   | С                                     |
|   | Iran Air Tours<br>ung sideways when it lan  | Tupolev Tu-154M (EP-MCF)<br>aded on runway 14L, skidded and ender   | Mashhad airport, Iran<br>d up in flames. Early reports suggest a   | -/28<br>nosewheel problem   | 11/148   | L                                     |
| panel and som<br>inoperative, bu<br>isolated one of                 | ght instrument displays, the<br>e of the centre console. T<br>t with the auxiliary power<br>the two main AC busbars | Airbus A319 (G-EZAC)<br>he upper ECAM screen, the autopilot an<br>l'he aircraft was en route from Alicante,<br>unit generator online as a substitute. A<br>s and others. The crew continued to Bri<br>The AAIB has recommended that Airbu                       | Spain to Bristol, UK. It had been dispa<br>faulty integrated monitoring unit misdi<br>istol and landed with no communication                                     | atched with one of its<br>agnosed an electrica<br>ns except the signal                | integrated drive ger<br>I system fault and au<br>via the standby trans | erators<br>utomatically<br>sponder on |
|   | one of its Airbus A319s   | Airbus A319 (N882MX)<br>struck power lines on final approach to<br>ort and maintenance infrastructure avai  |  |   |  |                                       |
| During its take<br>borne, but imm                                   | ediately returned to land   | Tupolev Tu-154 (EX-85718)<br>a Boeing KC-135 that was vacating the<br>at Bishkek without further incident. All p<br>fire. None of the three crew on board t   | passengers and crew were safely evac   | n of its outer starboa  |  |                                       |
| 3 October<br>The aircraft lar                                       | Mandala Airlines<br>ded in poor visibility caus   | Boeing 737-200 (PK-RIE)<br>sed by smoke from forest fires and veer  | Tarakan Juwata airport, Indonesia<br>red off the side of the runway, sustainir   |   | 6/104  | L                                     |
|   |   | Boeing 757<br>pproach half an hour after sunset to rur<br>he northern side of, and is parallel to, r  |  | -/-<br>a. According to the F/   | <b>6/157</b><br>AA's eastern region,                                   | L<br>the aircraft                     |
| <b>30 October</b><br>The aircraft de                                | Continental Airlines  | Boeing 757<br>nway. Flight AS61 to Juneau, Alaska wa  | Seattle Tacoma airport, WA, USA<br>as assigned runway 34C, but it took of  |   | <b>67</b><br>way 34R.  | то                                    |
| The aircraft ret  |   | Boeing 777-200ER<br>ke-off when debris emerged from the Na<br>es not appear to have been caused by t  |  | no flightdeck alerts,   |  |                                       |
| 16 December   | Gainjet   | Boeing MD-83 (SX-IFA)<br>g after an electrical fire started on the fl   | Midway airport, IL, USA  | -   | ?  | ER                                    |
| 21 December   | Southwest Airlines  | <b>Boeing 737</b><br>g with smoke in the flightdeck.  | Wichita, KS, USA   | -   | ?  | ER                                    |
| 22 December   | • • •   | Airbus A319   | Bristol airport, UK  | •   | ?  | L                                     |
|   | Champion Air<br>aulic system failure the cr   | Boeing 737-200<br>rew made an emergency landing.  | Kinston airport, NC, USA   | -/-   | ?/140  | ER                                    |
| 24 December   |   | Boeing 737-400 (PK-LIJ)   | Makassar, Indonesia  | -/-   | 6/156  | L                                     |
|   | Mandarin Airlines   | Fokker 100  | Taipei, Taiwan   | -/-   | ?  | то                                    |
| 26 December   | British Airways   | Boeing 747-400<br>area and damaged approach lights, but   | Miami airport, FL, USA<br>was undamaged. The operator says to  | -/-<br>axiway exit markings   | ?<br>were too worn for th  | L<br>le pilot to se                   |
|   | JetBlue Airways   | Airbus A320-200   | Long Beach airport, CA, USA  | -/-   | ?/154  | TO                                    |

|   | /  |   |  |                     |                         |                 |
|---|--|---|--|---------------------|-------------------------|-----------------|
| Date  | Carrier  | Aircraft type/registration  | Location   | Injuries            | Total occupants         | Phase           |
|   |  |   |  | crew/pax            | crew/pax                |                 |
| NON-FATAL                                   | ACCIDENTS AND INCID                            | DENTS, NON-SCHEDULED PASSENG  |  |                     |                         |                 |
|   |  |   |  | -/-                 | ?/?                     | RA              |
|   | Mahan Air                                      | Airbus A310-300 (F-OJHI)<br>ch to runway 33, was instructed to go a                       | Birmingham, UK   |                     |                         |                 |
|   |  | ut 600ft AGL when it should have been   |  |                     | while suil tokin hon    | i the all port. |
| 5 March                                     | SASCA  | Cessna 208B Caravan (YV-1149C)  | Nr Arekuna Camp, Venezuela                               | ?/?                 | 2/11                    | ER              |
|   |  | from 10,000ft looking for a forced landi  |  |                     |                         |                 |
| 18 March                                    | Air Algerie                                    | Boeing 737-600 (7T-VJQ)   | Seville airport, Spain                                   | -/45                | 7/101                   | I I             |
|   |  | ng crosswind from the left, the aircraft v  |  |                     |                         | Le and the      |
|   |  | estigators say the right main gear collaps  |  |                     |                         |                 |
| 1 May                                       | Trans Capital Air                              | DHC Dash 7-100 (C-GLPP)   | Zwedru airport, Liberia                                  | - /-                | 3/37                    | 1               |
|   | anded with the gear up.                        | Brie Basil Fried (G-GEIT)   | Zweard anport, Eiberia                                   | - /-                | 5,51                    | -               |
| 31 July                                     | Ward Air                                       | DHC Twin Otter (N93356)   | Berners Bay  | -/-                 | 1/6                     |                 |
|   |  | ers to their worksite, was attempting to  |  |                     |                         | d nosed         |
|   | cupants escaped via the at                     |   |  |                     |                         |                 |
| 28 August                                   |  | GAF Nomad (ZP-TDZ)  | Nr Cerrillos, Argentina                                  | -/-                 | 2/10                    | RA              |
|   |  | ward Salta caused the captain to decide   |  |                     |                         |                 |
| 30 October                                  | Aerotucan                                      | Cessna Caravan (XA-UBL)   | Punta Parajos, Mexico                                    | -/-                 | 2/12                    | С               |
|   |  | d at Punta Parajos airfield. but did not g  |  |                     |                         | -               |
|   | understorm activity nearby                     |   |  |                     |                         | agoom           |
|   | Goma Air                                       | Let L-410UVP (9Q-CBQ)   | Walikale, DR Congo                                       | -/-                 | 2/2                     | L               |
|   |  | a road near Walikale, had to return with  |  |                     |                         | _               |
|   | r Aboitiz Air                                  | NAMC YS-11  | Ninoy Aquino airp't, Manila, Philippines                 |                     | 4/5                     | L               |
|   |  |   | • • • • • •  |                     |                         | -               |
|   |  | the right and the right main gear collaps   |  |                     |                         |                 |
|   |  | DENTS, REGIONAL AND COMMUTE   |  |                     |                         |                 |
| 2 January                                   | American Eagle                                 | Saab 340B   | CA, USA  | -/-                 | 3/25                    | С               |
|   |  | s Angeles, the crew lost control and the  |  |                     |                         |                 |
|   |  | ne NTSB notes that the de-icing system w  |  |                     |                         |                 |
|   |  | systems operated, the autopilot tripped o<br>aircraft continued to its original destinati |  |                     | raπ began losing nei    | gnt. The cap-   |
|   |  | •   |  |                     | <b>0</b> ///            |                 |
| 10 January                                  | NatureAir                                      | DHC Twin Otter (TI-BAF)   | Puerto Jimenez airport, Costa Rica                       |                     | 2/11                    | то              |
|   |  | se of tyre failure during the take-off run.   |  |                     |                         |                 |
| 26 January                                  | Swiss  | Embraer ERJ-145   | Stuttgart airport, Germany                               | -/-                 | 3/40                    | L               |
|   |  | ut 20m in light snow, according to Swiss  | <ol> <li>The initial assessment suggested the</li> </ol> | ere was no damage,  | so after the aircraft h | ad been         |
|   | •  | inder its own power to the stand.   |  |                     |                         |                 |
| 2 March                                     | Blue Airways                                   | Antonov An-2  | Lubanimanga, DR Congo                                    | -/3                 | 1/5                     | ER              |
| Crash or forc                               | •  |   |  |                     |                         |                 |
| 11 March                                    | Air Deccan                                     | ATR 72-200 (VT-DKC)   | Bangalore airport, India                                 | - /-                | 4/40                    | L               |
| -   |  | ft was damaged beyond economic repa   |  |                     |                         |                 |
| 19 March                                    | Pinnacle Airlines                              | Bombardier CRJ440 (N8783E)  | Asheville airport, NC, USA                               | -/-                 | 3/30                    | C               |
|   |  | Detroit there was a fire in a windscreen  |  |                     |                         |                 |
|   |  | w returned to Asheville. The aircraft was   |  |                     | · ·                     |                 |
| 29 April                                    |  | Embraer ERJ-145 (N811HK)  | Springfield, MO, USA                                     | -/2                 | 3/30                    | ER              |
|   |  | Airlines for American Connection, was e<br>e is still under investigation.                | n route from Austin, Texas to St Louis,                  | Missouri. The crew  | diverted to Springfield | d, when they    |
|   |  | 0   |  |                     |                         |                 |
| 1 May                                       | United Nations                                 | DHC Dash 7 (C-GLPP)   | Zwedru airport, Liberia                                  | -/-                 | 3/37                    | L               |
|   | Ŭ  | ed from Trans Capital Air and was carryi  |  |                     | A/1.5                   |                 |
| 2 May                                       |  | Embraer ERJ-145XR   | Houston int airport, TX, USA                             | -/-                 | 3/45                    | TO              |
|   | • • •  | ake-off. The pilots of the ExpressJet-ope   |  |                     | •                       | k at Houston.   |
| 21 May                                      |  | n Beech 1900D (N69549)  | Fort Lauderdale, FA, USA                                 | -/-                 | 3/20                    | L               |
| Ū   | 0  | ng. The flight from Andros Town in the B  | 0 1  |                     |                         | onal Airlines.  |
| 30 May                                      | United Express                                 | Embraer 170-100LR (N651RW)  | Washington Dulles airport, VA, USA                       |                     | 4/56                    | L               |
|   |  | ed flight from Houston announced an en  |  |                     |                         | ay 19L with     |
|   | •  | The passengers disembarked via the rea  |  |                     |                         |                 |
| 1 June                                      | Air Panama                                     | BAe Jetstream 31 (HP1477PS)   | Bocas Del Toro airport, Panama                           | -/-                 | 2/16                    | L               |
|   | overran the wet runway and                     | d came to rest in marshy ground.  |  |                     |                         |                 |
| 5 June                                      | Merpati Nusantara                              | EADS Casa C-212 (PK-NCL)  | Banda airport, Maluku, Indonesia                         |                     | 3/14                    | L               |
|   |  | ded off the runway during a landing in he   | eavy rain. Merpati says the aircraft was                 | not seriously damag | led, but local press re | eports said     |
|   | mage to the wings, underc                      |   |  |                     |                         |                 |
| 22 June                                     | City Star Airlines                             | Dornier 328 (TF-CSB)  | Aberdeen airport, Scotland, UK                           | -/-                 | 3/16                    | L               |
|   |  | Norway, overran runway 34. No-one was   |  |                     |                         |                 |
|   |  | ure pilots are trained to handle similar si<br>o release the latches. The UK AAIB says    |  |                     |                         |                 |
| -   |  |   |  |                     |                         | G               |
| 15 July<br>While the ER                     |  | Embraer ERJ-135ER (F-GOHC)  | Madrid Barajas airport, Spain                            | -/-                 | 3/-                     | -               |
|   |  | ai Airways Boeing 747-400 taxiing from  |  |                     | , mung it with its rigr | e wingup.       |
| 26 July                                     | Mesa Airlines                                  | Bombardier CRJ  | Los Angeles airport, CA, USA                             | -/-                 | ?                       | G<br>ning off   |
|   |  | Brasilia narrowly averted a crash at Los<br>nal jet – operating for America West Exp      |  |                     |                         |                 |
|   |  | the turboprop crew took-off with less that  |  |                     |                         |                 |
|   |  | t's control tower-based Airport Movemer   |  |                     |                         |                 |
| Tom. The FA                                 |  |   |  |                     |                         | L               |
|   | Perimeter Airlines                             | Swearingen Metro II (C-ETNV)  | Norway House airport Canada                              |                     |                         |                 |
| 8 November                                  | Perimeter Airlines                             | Swearingen Metro II (C-FTNV)<br>o rocky terrain severely damaging the ur                  | Norway House airport, Canada                             | -/-                 | 2/7                     |                 |
| 8 November<br>The aircraft s                | werved off the runway onto                     | o rocky terrain severely damaging the ur  | ndercarriage.  |                     |                         |                 |
| 8 November                                  | werved off the runway onto<br>Falkland Islands |   |  |                     | 1/2                     | L               |
| 8 November<br>The aircraft s<br>19 November | werved off the runway onto                     | o rocky terrain severely damaging the ur<br>B-N Islander (VP-FBI)                         | ndercarriage.  |                     |                         |                 |

| Date  | Carrier  | Aircraft type/registration   | Location   | Injuries<br>crew/pax  | Total occupants<br>crew/pax                          | Phase  |
|---|--|--|--|---|--|--|
|   | Sudan Airways<br>ered off the runway, repor  | Fokker 50 (ST-ASJ)<br>rtedly following nose gear failure.  | Kenana, Sudan  | -   | ?  | L  |
| 13 December   | Air South West<br>in gear wheels fell off dur  | DHC Dash 8-300 (G-WOWD)  | Newquay, UK  | -   | ?  | то   |
| 28 December   | 0  | BN Islander (ZK-WNZ)   | Tauranga, New Zealand  | -/-   | ?/?  | L  |
| NON-FATAL   | ACCIDENTS AND INCID  | ENTS, NON-PASSENGER FLIGHTS  |  |   |  |  |
|   |  | <b>Douglas C-54 (C-GXKN)</b><br>there was a fire in the No 2 engine. The<br>ding. When the fire indications stopped t  |  |   |  |  |
| 24 January<br>The landing wa  | Aerolift<br>as so hard both main wing  | Antonov An-12<br>g spars fractured.  | Mbuji Mayi airport, DR Congo   | -   | 4  | L  |
| <b>25 January</b><br>The pilot was o                                  | Aero Tropics   | Cessna 208B Caravan (VH-WZJ)<br>est flight , but overran the runway and cr   | Caloundra airport, Australia<br>rashed through a fence damaging the a  | -<br>ircraft.   | 2  | L  |
| 25 January<br>The aircraft wa   | Cargolux<br>as due to fly out of Shang   | Boeing 747-400 (LX-TCV)<br>hai, but Cargolux says the nose gear wa   | Shanghai, China<br>as retracted while the aircraft was unde  | -<br>rgoing ground servici  | ng. No-one was inju                                  | G<br>red.                                    |
| to allow air-to-a   | air photographs of each a  | Shorts 360-300 (N372AC)<br>Intenance test flight at the same time as a<br>incraft to be taken. During this exercise  | they collided. This aircraft suffered dam  | age, a total loss of h  | ydraulic pressure, ar                                | nd the crew                                  |
| 8 February<br>Just after clear<br>aircraft on land<br>ed clearance to | United Parcel Services<br>rance to land on Philadelp<br>ding. ATC recleared the ai<br>o land on 27R, which was | ol, the crew diverted to Juneau-Dodge (<br>McDonnell Douglas DC-8-71F<br>bhia's runway 27R, the crew received a<br>rcraft for the longer 27L, but the crew m<br>s approved. The aircraft was emitting sm   | Philadelphia airport, PA, USA<br>smoke warning from the cargo hold and<br>issed the change and remained lined u<br>toke on landing, and although fire crew | d asked ATC to have<br>p on 27R. When ATC<br>s extinguished the bla | 3<br>fire/rescue services<br>C queried this, the cre | L<br>meet the<br>ew request-<br>written off. |
|   | SAS Commuter<br>nance on the stand before  | Fokker 50 (LN-RND)<br>e departure, the main gear was accident  | Oslo Gardemoen airport, Norway<br>tally retracted, reports SAS, damaging t   |   | re no injuries.                                      | G  |
|   | Wimbi Dira Airways<br>le of the runway and caug  | Antonov An-12<br>ght fire.   | Mbuji Mayi airport, DR Congo   | -   | 6  | L  |
|   |  | <ul> <li>Douglas DC-3 (N777YA)<br/>nage when it hit trees on approach to Be<br/>v it.</li> </ul>   | Beluga, AK, USA<br>eluga. The aircraft was subsequently flo  | -<br>wn to Anchorage des  | 2<br>spite the damage, wh                            | L<br>nich was                                |
| 17 March<br>Overran the ru  | Trackmark Cargo  | BAe HS748-2A (5Y-TCA)<br>ercarriage failed.  | Old Fangak, Sudan  | ?   | ?  | L  |
|   |  | Antonov An-12 (EK-46741)<br>Arab Emirates, the crew reported they<br>up and caught fire. Multiple birdstrike is  |  | -<br>t of four engines faile  | <b>12</b><br>d. The aircraft was fo                  | C<br>prced to put                            |
| 29 March<br>Overran the ru  | Cen-Sad<br>Inway in heavy rain and b   | Ilyushin II-62M (5A-DKR)<br>roke into large sections. The aircraft is c  | Moscow Domodedovo, Russia<br>configured in VIP lay-out and owned by  | -<br>the Community of Sa  | 6<br>ahel-Saharan States                             | L<br>(Cen-Sad).                              |
|   |  | McDonnell Douglas DC-10-10F<br>to Seattle, climbed through FL300, its No<br>field in Arkansas. The aircraft suffered s   |  |   |  |  |
| 4 May<br>The aircraft wa  | Transmile Airlines   | Boeing 727-200F (9M-TGA)<br>e afternoon on a hot clear day when ther   | Bangalore airport, India   | tank, says the airline  | ?<br>. causing "extensive"                           | G<br>fire damage                             |
| 4 June  | Arrow Air  | McDonnell Douglas DC-10-10F  | Managua airport, Nicaragua   | -   | 3  | L  |
| 7 June  | Tradewinds Int'l   | ut 350m and broke through the perimete<br>Boeing 747-200F (N922FT)<br>use of engine problems, but overran the  | Medellin airport, Colombia   | -   | 5  | то   |
| <b>15 June</b><br>Although boun<br>where the airc                     | TNT Airways<br>Id for London Stansted ai<br>raft touched down so hea   | Boord of a state of the state o | Birmingham airport, UK<br>there was below minima they annou<br>landing gear broke off. The crew mana   | unced a diversion to ged to carry out a m                           | issed approach and                                   |  |
| 12 July   | Transafrik   | Lockheed L-100-30 (S9-BOF)<br>pone around from a first attempt at landin   | Kigoma airport, Tanzania   | -   | 5  | L<br>Vere damage                             |
| <b>19 July</b><br>The left engine                                     | Tol Air Services<br>e lost power at about 100  | Douglas DC-3 (N782T)<br>ft after take-off and the aircraft would no  | St Thomas, US Virgin Islands<br>ot maintain height and speed. The capt   | -   | 4  | С  |
| 23 July<br>The NTSB beli<br>occurred at ab                            | Atlas Air<br>ieves a controller error ca<br>out 22:00 when the Atlas   | the occupants disembarked into the life<br>Boeing 747<br>used a runway incursion at Chicago O'I<br>freighter crossed runway 27L (after lanc  | Chicago O'Hare airport, IL, USA<br>Hare involving a United Airlines Boeing<br>ding on 14R) after United flight 1015 wa                                     | is cleared for take-off   | f. The agency says th                                | ne 737 took                                  |
|   | <b>.</b> ,   | imating the aircraft came within 60-90m<br>measurement between the widebody's<br>McDonnell Douglas DC-10-10 (N391FE)   | tail and the 737's undercarriage.  |   | e between the fusela                                 | ges as the                                   |
| The left main g   | gear collapsed during land<br>United Nations   | ding and fire broke out in the left wing ar<br>Cessna Caravan (5Y-NPD)   | nd engine.<br>Sudan  |   | 3  | ER   |
| Forced landing  | following engine problen   |  | Caticlan Malay airport, Philippines  |   | 3  | L  |
|   | yreburst on landing cause  | ed the aircraft to veer off the runway and<br>Swearingen Metro III (LV-WRA)  |  |   | 2  | то   |
| The aircraft ba   |  | un, a wingtip struck the ground and the  |  |   | 1  | L  |
| Gear collapsed  | d.   | . ,  |  |   |  |  |
| When the aircr  |  | Boeing 747-200F (N752SA)<br>a departure the crew returned to Anchora<br>n caused by a vehicle during de-icing.   | Anchorage, AK, USA<br>age, where it was found there was a 1n   | -<br>n-long gash in the fus   | ?<br>selage that had not b                           | C<br>een reporte                             |